

In re Patent of:)
NORIBUMI KOITABASHI ET AL.	: Examiner: Thinh H. Nguyen)
22.00.00.00.00	: Group Art Unit: 2861
Appln. No.: 09/845,498	: Certificate
Filed: May 1, 2001) SEP 1 5 2005
For: RECORDING APPARATUS AND METHOD	of Correction
U.S. Patent No.: 6,908,176 B2) :
Issued: June 21, 2005) September 8, 2005

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION <u>UNDER RULES 322 AND 323</u>

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

09/12/2005 EAYALEW1 00000043 6908176

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Elizabeth F. Holowacz Attorney for Patentees Registration No. 42,667

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

522821v1

CERTIFICATE OF CORRECTION

PATENT NO.

6,908,176 B2

DATED

June 21, 2005

INVENTOR(S) :

NORIBUMI KOITABASHI ET AL.

Page 1 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 23

FIG. 29B, "DENITY" should read --DENSITY--FIG 29C, "THRESHULD" should read --THRESHOLD--.

COLUMN 1

Line 5, "relate" should read --relates--;

Line 7, "element" should read --elements--; and "predetermine" should read --predetermined--; and

Line 32, "ejection failure." should read -- "ejection failure." --.

COLUMN 2

Line 44, "accomplish" should read --accomplishing--.

COLUMN 3

Line 4, "element" should read --elements--; and Line 31, "element" should read --elements--.

COLUMN 4

Line 47, "by of" should read --by--; and Line 61, "bade" should read --bad--.

MAILING ADDRESS OF SENDER:

PATENT NO. US 6,908,176 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

522821v1

■> _____

1 9 2005

CERTIFICATE OF CORRECTION

PATENT NO.

6,908,176 B2

DATED

June 21, 2005

INVENTOR(S) :

NORIBUMI KOITABASHI ET AL.

Page 2 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 5

Line 17, "pi-inter" should read --printer--;

Line 32, "out" should read --output--; and

Line 44, "In" should read --in--.

COLUMN 6

Line 24, "records" should read --record--; and

Line 56, "(Y)ink," should read --(Y) ink,--.

COLUMN 7

Line 12, "on," should read --on--; and

Line 57, "recorded" should read --recorded.--.

COLUMN 8

Line 12, "nozzle," should read --nozzles--; and

Line 66, "narrower" should read --narrow--.

COLUMN 10

Line 19, "color" should read --color.--.

COLUMN 11

Line 30, "becomes" should read --become--; and

Line 66, "is" should read --are--.

MAILING ADDRESS OF SENDER:

PATENT NO. US 6,908,176 B2

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

522821v1

=>

No. of add'l. copies

@ 30¢ per page

CERTIFICATE OF CORRECTION

PATENT NO.

6,908,176 B2

DATED

June 21, 2005

INVENTOR(S) :

NORIBUMI KOITABASHI ET AL.

Page 3 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12

Line 54, "In" should read --in--.

COLUMN 13

Line 1, "Read" should read --Head--;

Line 38, "nozzles" should read --nozzle--;

Line 41, "nozzles" should read --nozzle--;

Line 48, "3/4 (76%) 3" should read --3/4 (76%),--;

Line 62, "time" should read --times--; and "Indicated" should read --indicated--.

COLUMN 15

Line 12, "portion 44" should read --portion 44.--;

Line 15, "direction" should read --direction.--;

Line 16, "In" should read --in--;

Line 33, "rail 11" should read --rail 11.--;

Line 38, "nest" should read --next--; and

Line 54, "ling" (both occurrences) should read --line--.

COLUMN 16

Line 47, "be also" should read -- also be--.

COLUMN 18

Line 20, "need" should read --needs--; and

Line 60, "nozzle," should read --nozzles,--.

MAILING ADDRESS OF SENDER:

PATENT NO. US 6,908,176 B2

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

No. of add'l. copies

@ 30¢ per page

🤈 🧝 g 2005

522821v1

CERTIFICATE OF CORRECTION

PATENT NO.

6,908,176 B2

DATED

June 21, 2005

INVENTOR(S) :

NORIBUMI KOITABASHI ET AL.

Page 4 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 19

Line 29, "fare" should read -- are--.

COLUMN 20

Line 25, "be also" should read -- also be--; and

Line 43, "nozzles" should read --nozzles.--.

COLUMN 21

Line 9, "human" should read --the human--;

Line 24, "process" should read --processed--;

Line 44, "increase," should read --increases,--;

Line 60, "nozzle." should read --nozzles.--; and

Line 65, "column" should read --columns--.

COLUMN 22

Line 61, "In" should read --in--; and

Line 67, "line" should read --in line--.

COLUMN 23

Line 15, "affect" should read --effect--;

Line 44, "computations" should read --computations.--; and

Line 64, "γ-reconversion" should read --γ-conversion--.

MAILING ADDRESS OF SENDER:

PATENT NO. US 6,908,176 B2

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

522821v1

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

6,908,176 B2

DATED

June 21, 2005

INVENTOR(S) :

NORIBUMI KOITABASHI ET AL.

Page 5 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 24

Line 6, "Nest," should read --Next,--; and Line 15, "of the a" should read --of the--.

COLUMN 25

Line 31, "c(and" should read --c and P--; and

Line 35, "becomes" should read --become--.

COLUMN 26

Line 32, "y conversion" should read --γ-conversion--.

COLUMN 28

Line 22, "dose" should read --do--;

Line 25, "the" (second occurrence) should be deleted;

Line 30, "nozzles" should read --nozzle--;

Line 60, "compared" should read --compare--; and

Line 65, "corresponds" should read --correspond--.

COLUMN 29

Line 12, "a" should be deleted; and "time" should read --time.--;

Line 16, "made," should read --made.--; and

Line 39, "color." should read --color,--.

MAILING ADDRESS OF SENDER:

PATENT NO. US 6,908,176 B2

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

No. of add'l. copies

@ 30¢ per page

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,908,176 B2

DATED

June 21, 2005

INVENTOR(S) :

NORIBUMI KOITABASHI ET AL.

Page 6 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 31

Line 13, "is" (first occurrence) should read --of--.

MAILING ADDRESS OF SENDER:

PATENT NO. US 6,908,176 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

522821v1

